

Deviation From Design	
DfD : DfD-0004	Taran Laval – SAAA Builder 7417 Van's Aircraft RV7 - 73918
RH HS404 Flange Damage	

BACKGROUND:

After riveting RH HS-404 a small mark from the rivet set (smiley face) was found on the flange.

ACTION TAKEN:

Marks on LS RS-404 flange were removed using red scotchbrite and alodine 1132 pen and primer was reapplied.