

Deviation From Design

DfD : DfD-0005

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**


RH HS404-HS710-HS405 Hole Elongation

BACKGROUND:

During removal of the RH HS404 the upper rivet hole become elongated.

ACTION TAKEN:

Drilled upper RH HS404 hole to 5/32 and installed a – 5 rivet.



Date: 19 APR 12