

Deviation From Design

DfD :

DfD-0016

Follow Up
Required

N

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**

LH ELEVATOR HOLE CRACKING

BACKGROUND:

**WHILE RIVETING LH ELEVATOR TOGETHER, OUTBOARD UPPERMOST DIMPLE
#1 & #7 FROM FRONT CRACKED WHEN RIVETING,**

ACTION TAKEN:

REMOVED DAMAGED MATERIAL, INSTALLED NAS1097AD4-4 (OOPS) RIVET



Date:

03 APR 2014