

Deviation From Design

DfD :

DfD-0020

Follow Up
Required

N

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**

LH WING MAIN RIB TO FWD SPAR DAMAGE



BACKGROUND:

DURING WING RIB TO MAIN SPAR RIVETING THE BUCKING BAR SLIPPED AND CONTACTED SPAR CAUSING A SMALL SCRATCH IN TWO LOCATIONS

- RIB 5 CENTER RIVET
- RIB 9 SECOND RIVET FROM BOTTOM

ACTION TAKEN:

RIVETS REMOVED SMALL SCRATCHES BLENDED/SPOT ALODINED AND RIVETS REINSTALLED



Date:

DD MMM YY