

Deviation From Design

DfD :

DfD-0023

Follow Up
Required



Y

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**

RIGHT WING REAR SPAR CORROSION

BACKGROUND:

DURING UNPACKAGING OF RIGHT HAND WING REAR SPAR, MULTIPLE SMALL AREAS OF LIGHT SURFACE CORROSION WAS FOUND



ACTION TAKEN:

- AREAS BLENDED WITH SCOTCHBRITE, ALL CORROSION REMOVED,
- SPAR CHANNEL WILL BE ALUMIPREPPED, ALODINED & PRIMED SHORTLY
- FOLLOW UP INSPECTION TO BE CARRIED OUT DURING ANNUAL CHECKS.

UPDATE 16 FEB 16

- REAR SPAR CHANNEL ALUMIPREPPED, ALODINED & PRIMED



Date:

15 FEB 16