

Deviation From Design

DfD :

DfD-00026

Follow Up
Required

Y

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**

LH FUEL TANK ATTACH SCREW DIMPLE CRACKS

BACKGROUND:

FOUND THAT 3 INBOARD-MOST SCREW HOLES ON UPPER LEFT HAND TANK ARE
ELONGATED AND CRACKED



ACTION TAKEN:

CONTACTED VAN'S, DECIDED TO STOP DRILL CRACKING

FOLLOW UP ACTION:

INSPECT STOP DRILL HOLES PERIODICALLY FOR ANY PROPOGATION OF CRACKS

Date:

27 MAY 16