

Deviation From Design

DfD : DfD-0001

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**

HS411 Bearing Assembly - Change of Recommended Rivet

BACKGROUND:

On the HS411 Bearing Assembly Van's recommends the use of an AN470AD4-5 Rivet, and the AN470AD4-5 rivet is not of sufficient length to produce a satisfactory shop head.

ACTION TAKEN:

The AN470AD4-5 rivet was interchanged with an AN470AD4-6 rivet.



Date: 15 JUL 11