

Deviation From Design

DfD : DfD-0003

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**


Minor Rivet Set Damage to HS-710

BACKGROUND:

During riveting of HS-710 – HS702 – HS405 the rivet set slipped and left very minor marks on the HS-710.

ACTION TAKEN:

Sharp edges on marks were blended to remove any possible stress raisers.



Date: 14 Apr. 12