

Deviation From Design

DfD : DfD-0009

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**


VS Oversize Hole

BACKGROUND:

At 702-704-801PP RHS Intersection wrong rivet was installed, in trying to remove wrong rivet hole became oversized

ACTION TAKEN:

I Elected to Install a NAS109AD4-5 (Oops) Rivet.



Date: 25 NOV 12