

Deviation From Design

DfD :

DfD-0013

Follow Up
Required

N

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**

LH HORIZ SATB RIVET HOLE ELONGATION

BACKGROUND:

DURING INITIAL ATTEMPTS AT RIVETING A HOLE IN THE LH HS707 – HS601PP A
HOLE BECAME ELONGATED

ACTION TAKEN:

INSTALLED AN NAS109AD4-4 (OOPS) RIVET

Date:

31 MAY 2013