

Deviation From Design

DfD :

DfD-0014

Follow Up
Required

N

Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918


RH ELEVATOR COUNTERSINK ELONGATION

BACKGROUND:

WHILE COUNTERSINKING SPAR 702 TO RIB 709 COUNTERSINK CHATTERED AND OVERCOUNTERSUNK 2 OF THE 4 HOLES

ACTION TAKEN:

DRILLED 2x 709 IB HOLES TO MATCH AND WILL FIT AN426**AD4**-4 RIVETS



Date:

28 FEB 14