Deviation From Design

DfD :	DfD-0015	Follow Up Required	Taran Laval – SAAA Builder 7417 Van's Aircraft RV7 - 73918
		N	

ELEVATOR RHS AFT UPPER HOLE RIVET CHANGE

BACKGROUND:

AFT MOST UPPER TIP RIB HOLE INACCESSABLE FOR RIVETING



ACTION TAKEN:

INSTALLED MK-319-BS BLIND RIVET IN ONE LOCATION