

Deviation From Design

DfD : **DfD-0017**

Follow Up
Required


N

**Taran Laval – SAAA Builder 7417
Van's Aircraft RV7 - 73918**

LH ELEVATOR RIVET CHANGE

BACKGROUND:

AFT MOST UPPER TIP RIB HOLES INACCESSABLE FOR RIVETING



ACTION TAKEN:

INSTALLED MK-319-BS BLIND RIVET IN TWO LOCATIONS

